

N. 34th Street / Former Production Plated Plastics

**Update Meeting
April 11, 2019**

Nathan Whitmyer, Project Manager

Michigan Department of Environmental Quality

Remediation and Redevelopment Division

Kalamazoo District Office



Work Completed Since Town Hall Meeting

- Installed and operating emergency PFAS treatment system
- Sampled 115 residential wells
 - Non-detect for PFOS + PFOA (73 wells)
 - ≤ 70 ppt PFOS + PFOA (26 wells)
 - > 70 ppt PFOS + PFOA (16 wells)
- Currently conducting Remedial Investigation (21 nested sets of monitoring wells have been installed to date)

Work Completed Since Town Hall Meeting

- Sampled 55 monitoring wells
 - Non-detect for PFOS + PFOA (5 wells)
 - ≤ 70 ppt PFOS + PFOA (5 wells)
 - > 70 ppt PFOS + PFOA (45 wells)

Next Steps

- Complete Remedial Investigation activities
 - Monitoring well sampling
 - Surface water sampling
- Possible outcomes
 - Expand investigation area and/or residential well sampling
 - No further investigation needed
- Continue to work with local and state agencies, Richland Township, City of Kalamazoo, others
- Residents can view regular updates at www.facebook.com/KalamazooCountyHCS/ or visit www.kalcounty.com/hcs/pfasresponse.php.